


Environmental Monitoring Plus (RSE-B) Connectivity Diagram

Optional Remote Sensors - Connect via I/O Port



Door Position Sensor



Smoke Alarm Kit



Water Sensor



Power Fail Monitor



RSE-B

IP Address: _____

Remote Sensors

I/O Ports

GEIST

6Vdc Power

Ethernet

C 1 2 3 C

Activity Idle



Temperature Sensor



Temperature, Air Flow Humidity, & Dew Point

Optional Remote Sensors Connect via RJ12

Static IP Address for set-up and configuration



DLink® Web Enabled Camera

ETHERNET ETHERNET ETHERNET ETHERNET ETHERNET